

BUILDING SAFETY CERTIFICATE

Reference No.....1527/A.....

Date.....22/09/2016.....

This is to certify that **R K Vidyapeeth, Naraini (Banda),UP** is having proper infrastructure facilities and Building construction is safe for the students and other staff of the school. Building stability life Approx. 50 years.

This Certificate is issued after inspecting the school plant.

Signature with Seal :

सहायक अभियन्ता
निर्माण खण्ड-1, लो0नि0वि0
बाँदा

THIS SCHEDULE OF LAND ABOVE REFERRED TO

ALL THAT STATE AND PART OF LAND MEASURING ... (area of land in square meters) situated

in ... (Plot No. .../ Survey No. .../ Block .../ Village .../ District .../ State .../ and bounded as follows: North .../ East .../ West .../ South .../ DISTRICT MAGISTRATE/

REGISTERING AUTHORITY WITH

DISTRICT MAGISTRATE/ REGISTERING AUTHORITY WITH DESIGNATION

Name of Owner

Name of Officer

Date: .../.../...